

**Ionising Radiation (Medical Exposure) Regulations 2000 –  
IR(ME)R 2000**

HEYH Radiology Department

**Procedure Title**    **To Ensure That Accidental Or Unintended Doses To Patients From Radiological Practices Are Reduced As Far As Is Reasonably Practicable**

**Scope**                All radiographic x-ray examinations.

**Responsibilities**    It is the responsibility of the Imaging Services Manager to ensure that:

Regular preventative maintenance and repairs are undertaken on each item of equipment involved in the imaging process.

All staff are adequately trained and qualified.

Quality control procedures are in place, implemented and monitored.

It is the responsibility of all staff to identify equipment faults or procedural breakdowns which could lead to an accidental or unintended dose to a patient. These occurrences should be reported to their line manager to resolve.

- Procedure**
1. Patient identity checked, prior to any radiation exposure, by the operator.
  2. All equipment subject to regular preventative maintenance – to manufacturers and / or RPA advice.
  3. Equipment quality assurance programme in place as outlined in IPEM 91 and advised by the RPA.
  4. Equipment faults logged and reported to the Superintendent / Senior Radiographer.
  5. Equipment with known faults likely to cause patient overexposure must be taken out of use until repair by a service engineer. Written confirmation must be obtained that the unit is safe for clinical use. Alterations affecting patient dose must be checked by the Radiation Physics Department and certified fit for clinical use.
  6. All staff must undertake manufacturers or suitable in-house training before operating equipment for clinical use.

<b>Filename:</b>	HEYRAD06-Probability and Magnitude of Accidental or Unintended Doses to Patients are Reduced as Far as Practicable	<b>Page:</b>	1 of 2	<b>Authorised by:</b>	Mandy Hay
<b>Issue Date:</b>	14/01/2010			<b>Review Date:</b>	14/01/2012

**Ionising Radiation (Medical Exposure) Regulations 2000 –  
IR(ME)R 2000**

HEYH Radiology Department

7. All incidents must be reported using the DATIX system, with correct investigation and follow up procedures.
8. Incident investigation reports must be reviewed and appropriate action taken to minimise the risk of recurrence.
9. When examining patients the most appropriate equipment available must be selected and operated in accordance with manufacturers' tolerances and Trust and imaging department procedures.

<b>Filename:</b>	HEYRAD06-Probability and Magnitude of Accidental or Unintended Doses to Patients are Reduced as Far as Practicable	<b>Page:</b>	2 of 2	<b>Authorised by:</b>	Mandy Hay
<b>Issue Date:</b>	14/01/2010			<b>Review Date:</b>	14/01/2012